



Paint ; White, gloss finish

#### Notes:

- During adjustment of AC output voltage, the Load (Static bars or Nozzles etc.) should be connected to the output terminals and then adjust the high voltage output by confirming voltage using monitor terminals by AC voltmeter.
- During adjustment of DC output voltage for ion balance adjustment, use a CPM to confirm offset voltage at the test position.

題名 TITLE PowerUnit 150		尺度 SCALE 1/2	単位 UNITS mm	
材質 MATERIAL -	備考 NOTE Dimensional Drawing	作図 Dr. Y.Kanzaki	検図 Chk. M.Kawakita	日付 DATE 2015.06.15
シムコジャパン株式会社		設計図番 CODE 220	図面番号 DRAWING No. P141219062	